

Shire of Denmark - ACM Register - 2021

Building	Address	Assessment File No.	ACM Location	Risk Level (MAS)	Date of Last Inspection	Testing Conducted	Report Link	Inspected By	Friable ACM Found?	Comment and Control Measures	Reinspection Date	Removal Date
Scout Hall	Brazier St	A3035	South West Storeroom Electrical Dist. Box External - near Footy Hall External - under Kitchen	Low Very Low Medium Medium	Apr-21	Yes	REPORT	CCA/Envirospect	No	Leave and manage in-situ Encapsulate, label, leave and manage in-situ Arrange for removal by appropriate contractor Arrange for removal by appropriate contractor	Apr-22	TBA
Civic Centre Hall Complex	3 Strickland Street	A3116	External Equipment Store	Medium Low	Apr-21	Yes	REPORT	CCA/Envirospect	No	Label (as appropriate) and leave in-situ Leave and manage in-situ	Apr-22	N/A
Denmark Bowling Club	Cnr S/C Hwy & Fyfe St	A3069	No ACM Detected		Apr-21	No	N/A	CCA/Envirospect	No	Demolished and Re-built in 2016/2017 - No ACM detected	N/A	N/A
Denmark Cottage Industry Building	5 Mitchell St	A3117	No ACM Detected		Apr-21	Yes	REPORT	CCA/Envirospect	No	All asbestos removed in 2019 - No ACM detected (see report)	N/A	N/A
Soil Solutions, DNMK Earthworks, DNMK Haulage	832 South Coast Highway	A2228	Office Floor and Shelves Electrical Dist. Box	Very Low Very Low	Apr-21	Yes	REPORT	CCA/Envirospect	No	Arrange for removal by appropriate contractor Leave and manage in-situ	Apr-22	TBA
Denmark Museum	16 Mitchell St	A3256	Electrical Dist. Box	Very Low	Apr-21	Yes	REPORT	CCA/Envirospect	No	Label (as appropriate) and maintain in-situ	Apr-22	N/A
Denmark Pony Club	73 Beveridge Rd	A3189	No ACM Detected		Apr-21	Yes	REPORT	CCA/Envirospect	No	Updated March 2021 - No ACM detected (see report)	N/A	N/A
Depot - Office/Amenities	41 Zimmerman St	A3185	No ACM Detected		Apr-21	Yes	REPORT	CCA/Envirospect	No	Updated March 2021 - No ACM detected (see report)	N/A	N/A
Kentdale Hall	518 Parker Rd	A3125	Hall External Wall Electrical Dist. Box Hall Internal Wall Hall Internal Ceiling	Very Low Very Low Very Low Very Low	Apr-21	Yes	REPORT	CCA/Envirospect	No	Label (as appropriate) and maintain in-situ Label (as appropriate) and maintain in-situ Label (as appropriate) and maintain in-situ Leave and manage in-situ	Apr-22	N/A
Denmark Library	3 Strickland Street	A3116	No ACM Detected		Apr-21	Yes	REPORT	CCA/Envirospect	No	Updated March 2021 - No ACM detected (see report)	N/A	N/A
Lions Club Station Masters House	2A Inlet Drive/Crellin St	A5600	Toilets Ceiling	Low	Apr-21	Yes	REPORT	CCA/Envirospect	No	Leave and manage in-situ	Apr-22	N/A
Old Post Office (Spirit Of Play)	2B Inlet Drive/Crellin St	A5598	External Wall External Trim Internal Wall Internal Trim Internal Ceiling Eaves	Medium Medium Medium Low Very Low Very Low	Apr-21	Yes	REPORT	CCA/Envirospect	No	Label (as appropriate) and maintain in-situ Label (as appropriate) and maintain in-situ Label (as appropriate) and maintain in-situ Leave and manage in-situ Leave and manage in-situ Leave and manage in-situ	Apr-22	N/A
Parry's Beach Campground - Caretakers Cottage	Parry Rd	A2678	External Wall External Trim Internal Wall Internal Ceiling	Medium Medium Medium Medium	Apr-21	Yes	REPORT	CCA/Envirospect	No	Repair damage, encapsulate material and maintain condition Leave and manage in-situ Leave and manage in-situ Leave and manage in-situ	Apr-22	N/A
Parryville Hall	Cnr Mardo & S/C Hwy	A3066	External Walls Kitchen Internal Walls Hall Ceiling	Medium Medium Low	Apr-21	Yes	REPORT	CCA/Envirospect	No	Encapsulate material and maintain condition Encapsulate material and maintain condition Leave and manage in-situ	Apr-22	N/A
Peaceful Bay Caravan Park - Shop & Residence, Laundry, Café, Ablution Blocks	East Ave, Peaceful Bay	A3104	Shop External Walls Shop Shed Annex Wall Shop External Wall	High Medium Medium	Apr-21	Yes	REPORT	CCA/Envirospect	No	Arrange for removal by appropriate contractor Repair damage, encapsulate material and maintain condition Repair damage, encapsulate material and maintain condition	Apr-22	TBA
RSL Memorial Hall	54 Strickland St	A3097	No ACM Detected		Apr-21	Yes	REPORT	CCA/Envirospect	No	Updated March 2021 - No ACM detected (see report)	N/A	N/A
Tingledale Hall	976 Valley of the Giants Rd	A3057	External and Sub Floor External Walls Electrical Dist. Box	High Medium Low	Apr-21	Yes	REPORT	CCA/Envirospect	No	Arrange for removal by appropriate contractor Encapsulate material and maintain condition Label (as appropriate) and maintain in-situ	Apr-22	TBA
Slipway Shed	South Coast Hwy	A3030	Gable Ends (Walls) Gable Ends (Trim)	High Medium	Apr-21	Yes	REPORT	CCA/Envirospect	No	Encapsulate unpainted areas. Leave and manage in-situ Leave and manage in-situ	Apr-22	N/A
McLean Park Old Toilets	Brazier St	A3035	Internal Ceiling Internal Wall Electrical Dist. Box	Medium High Low	Apr-21	Yes	REPORT	CCA/Envirospect	No	Leave and manage in-situ Arrange for removal by appropriate contractor Leave and manage in-situ	Apr-22	TBA