Treatment ID 17947

| Location | Works Required in area Highlighted in red boundary |
|---|---|
| Hamilton Reserve, 72 South Coast Hwy. | Widen/maintain existing fire access tracks to a minimum of 4m wide where possible, and with 1m low fuel either side, plus remove over-hanging vegetation to 5m high.<br><br>Upgrade fire access track to trafficable surface by grading with existing scree. |
| **Treatment Type** | |
| Access track | |
| **Size of Area/Length of Track** | |
| 0.29 km | |