

MH9&10 -Treatment ID number 5742



Location	Works Required in area Highlighted in red boundary
Reserve Heather Rd and Allundora way	<ul style="list-style-type: none"> • Widen/maintain existing fire access tracks to a minimum of 4m wide where possible 1m low fuel either side, plus remove over-hanging vegetation to 5m high, all lopping's and materials to be removed from site. • Upgrade fire access track to trafficable surface by grading and or fill with gravel • Install water erosion treatments to reduce surface scouring under heavy rainfall. (refer document – Shire of Denmark Mitigation standards and terminology). • All disease risk protocols are to be followed (Phytophora). ((refer document – Shire of Denmark Mitigation standards and terminology). • Remove all debris and waste material from the reserve.
Treatment Type	
Fire access	
Size of Area/Length of Track	
700m	